



Technical Data

B1111

Aggressive Wood Floor Cleaner

Intensive Floor Treatment (I.F.T.) is the first step in a two-part cleaning system designed to prepare floors for the application of TyKote® in the TyKote Dust-Free Refinishing System. I.F.T. is a powerful cleaner designed to remove tough oil, dirt, and other residue from the floor. I.F.T. is a vital part of the preparation process and should never be omitted.

PROPERTIES

Color	Lavender (Light Purple)
Density	8.30 - 8.40 lbs/gallon
	12 – 14
VOC At minimum dilu	ution does not exceed 2% by weight
Flash Point	
Freeze/Thaw Stability	Stable
Packaging	1 US gallon plastic pail (4 per case)
	5 US gallon plastic pails
	55 US gallon plastic drum

APPLICATION METHOD

- To prepare the floor for the cleaning process, remove all caked mud, chewing gum and other debris from the floor. Vacuum the dirt from the floor. Pay special attention to corners.
- 2. Prepare a diluted solution of I.F.T. using 4 parts water to 1 part
- Soak several clean towels in the solution and wring them until nearly dry.
- 4. Wrap a towel around a push broom and tack the floor. To prevent redeposit of dirt and oil, refold towel using clean sides as needed. Pay special attention to corners.
- Repeat steps 3-4 in each area of the floor until the entire floor has been cleaned.
- 6. NOTE: For stubborn surface marks, dirt and shoe marks, use a moderately abrasive nylon pad or sponge moistened with diluted I.F.T. solution and scour area manually until spot is removed. Follow with a clean water rinse on scrubbed area.
- 7. Always rinse the floor by damp mopping with clean water and a clean mop until the rinse water is clean or use tack towels with clean water. Pay special attention to corners.
- 8. Clean the floor again using Basic Coatings® Squeaky™ cleaner, following the same cleaning procedure described above [Steps 2-4]. Since Squeaky cleaner does not leave a residue, no clear water rinse is needed after this step. The two cleaners are specifically formulated to remove different types of contaminants from the floor and may NOT be combined into a single treatment.

ALTERNATE APPLICATION METHOD

- Prepare a diluted solution of I.F.T. using 4 parts water to 1 part I.F.T. in a mop bucket.
- 2. Soak string mop in the solution and wring excess out.
- 3. Mop the floor paying special attention to corners. Resoak and wring mop frequently. Mop until the entire floor has been cleaned
- 4. Always rinse the floor by damp mopping with clean water and a clean mop until the rinse water is clean or use tack towels with clean water. Pay special attention to corners.
- 5. Clean the floor again using Squeaky cleaner, following the same cleaning procedure described above. Since Squeaky cleaner does not leave a residue, no clear water rinse is needed after this step. The two cleaners are specifically formulated to remove different types of contaminants from the floor and may not be combined into a single treatment.

AUTO-SCRUBBER APPLICATION METHOD

If using an automatic scrubber, use at a dilution rate of 8 oz. per gallon (1 part I.F.T. to 16 parts water) with a microfiber cleaning pad. Make sure squeegees and buffing pads work well. A person with a mop must follow behind the scrubber to pick up any water that is not picked up from the machine. Pay special attention to corners.

PRECAUTIONS

KEEP OUT OF REACH OF CHILDREN. FOR INDUSTRY USE.



WARNING! FLAMMABLE LIQUID AND VAPOR. CAUSES SERIOUS EYE IRRITATION. Wear protective gloves: 1 - 4 hours (breakthrough time): disposable vinyl. Wear eye or face protection: Recommended: safety glasses. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use explosion-proof electrical, ventilating, lighting and all material-handling equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Keep container tightly closed. Wash hands thoroughly after handling.



FIRST AID: IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. IF IN EYES: Rinse cautiously

with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention. Store in a well-ventilated place. Keep cool. Dispose of contents and container in accordance with all local, regional, national and international regulations.



©Basic Coatings • All Rights Reserved. • Worldwide Headquarters •1001 Brown Avenue • Toledo, Ohio 43607-0127 800-441-1934 • bcinfo@basiccoatings.com • www.basiccoatings.com

I.F.T. • 11.2015 • Page 1